

Air Cooler

Category	Iron Cooler (9"-18")	Iron Cooler (24")	Plastic Cooler
Cooler Installation (including Exhaust)	₹ 349	₹ 649	-
Cooler Uninstallation (including Exhaust)	₹ 249	₹ 549	-
Exhaust motor (uninstallation +installation)	₹ 399	₹ 999	₹ 599
Cooler Shifting (excluding Exhaust)	₹ 499	₹ 699	₹ 199
Cooler Installation/Fitting	₹ 249	₹ 499	₹ 199
Exhaust Repair	On Inspection	On Inspection	On Inspection
Painting	On Visit	On Visit	On Visit
Air Cooler Grass change	₹ 499	₹ 699	₹ 349
Seasonal Servicing	₹ 299	₹ 499	₹ 299
Fan blade Replacement	₹ 299	₹ 399	₹ 299
Water Pump Replacement	₹ 199	₹ 199	₹ 199

Key Highlights

1-If you are not going to repair the problem after technician inspection due to any reason, there will be minimum visiting charges Rs.200 for inspection.

2-This Rate card includes only labour charges. Spare Parts cost will be charged extra if used.

3-Actual Repair Cost will be provided after diagnosis.

4-All the rates mentioned in our rate card are exclusive of GST.

5- Get 30 Days of complete Warranty of Repair (T&C apply)*
(Warranty will be null and void in case of accidental damage)

6-We sell and service all the brands.